December 14, 2009 1:11:14 PM

Item ID:

D205-634-011

Accept

Setup Start



Revision ID:

Skidtube Item Name:

Required Date: 21/12/2009

Start Date:

14/12/2009

QC:

Start Qty: 1.00

Req'd Qty: 1.00

Cust Item ID:

Customer:

Reference:

Approvals:

Date:

SPC (Y/N):

Date: Date: Run

Stop

Start

Stop



Sequence ID/ Work Center ID

Operation Description Set Up/ **Run Hours**

Draw Number Draw Rev.

Code

Reject Accept Qty Qty

Reject Number Stamp

Insp.

Draw Nbr

Revision Nbr

IIN D205-634

Rev F

100

Document Control

Memo

0.00

0.00

Photocopy bluefile &type labels per PPP D205-634-011

CHG 007

110

Packaging

Packaging

Pick Kit

Memo

Memo

0.00

0.00

120

Quality Control

QC4- 100% Inspect kits for completeness

0.00

Dart Ae	rospace l	Ltd						<i>je</i> 1
W/O:			WC	RK ORDER CHANGES	S			
DATE	STEP	PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					B		3	
Part No):	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	Date: _	
	Re	solution:	Disposition	າ:	QA: N/C CI	osed:	Date: _	
NCR:			WORK ORDE	ER NON-CONFORMAN	ICE (NCF	R)		
DATE	0	Description of NC	Corrective Action Section B			Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspecto
		1000						
							+	+

NOTE: Date & initial all entries

December 14, 2009 1:11:14 PM

Required Date: 21/12/2009

Item ID: **Revision ID:** D205-634-011

Accept



Setup Start

Stop



Item Name: **Start Date:**

14/12/2009

Skidtube

Start Qty: 1.00

Req'd Qty: 1.00

Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Draw

Rev.

Plan

Code

Start Run

Reject

Qty _

Stop



Date:

SPC (Y/N):

Date:

Accept

Qty

Number Stamp

Reject

Sequence ID/ Work Center ID

130

Packaging

Packaging

140

Operation Description Set Up/ **Run Hours**

0.00

0.00

Identify and pack for shipping as per PPP D205-634-011

Location:

QC21- Final Inspection - Work Order Release

PPP rev:_

0.00



Quality Control

Memo

0.00

Dart Ae	rospace Li	d d						<i>jo</i> ≥ • •
W/O:			WORK ORDER	CHANGES	·			
DATE	STEP	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								:
				i				
								•
Part No:		PAR #:	Fault Category:	NCR: Yes No DQA: I		Date:		
	Resolution:		Disposition:	QA: N/C Closed:			Date: _	
NCR:		\	WORK ORDER NON-CON	FORMANCE (NO	CR)			
DATE	STEP	Description of NC	Corrective Action		Verif	ication	Approval	Approval

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC	Corrective Action Section B			Verification	Approval	Approval		
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC inspector		

NOTE: Date & initial all entries

Warehouse Loc Oty Loc Code Location Main Warehouse FG 1 47216 Main Warehouse PK 51657 2 51658 2

STEP	PRO	OCEDURE CHAN					1	Approval	
			NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
	•								
Reso	lution:	Disposition	1:	QA	N/C CI	osed:		Date:	
	•	WORK ORDE	ER NON-CONFORM	IANCE	(NCF	1)			
STEP	Description of NC Section A	Initial Chief Eng			Sign & Date			Approval Chief Eng	Approva QC Inspect
	Reso	Resolution: Description of NC Section A	Resolution: Disposition WORK ORDE STEP Description of NC Section A Initial Chief Eng	Resolution:	NORK ORDER NON-CONFORMANCE	Resolution:	Resolution: Disposition: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Corrective Action Section B Sign & Date Verific Section A Chief Eng Chief En	Resolution: Disposition: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Corrective Action Section B Sign & Date	STEP Description of NC Section A Corrective Action Section B Initial Chief Eng Chief

NOTE: Date & initial all entries